


1. Primary Seal Butyl
2. Secondary Seal Butyl
3. Metallized Silver Interlayer
4. Fill, Desiccant



MGM	INDUSTRIES	
	287 Fresh Hill Road	
Hendersonville, NC 27534		Phone: 704-475-5281
TITLE: Vertical and Horizontal Cross-Section MATERIALS: Series #8010 Double Hung DATE: 05-03-05 SCALE: DO NOT SCALE DRAWN BY: RGroves DWG NO.: 1 Page		